

# **Aviation Investigation Preliminary Report**

1 None

Location: Alpine, AR **Accident Number:** CEN24LA145

Date & Time: April 2, 2024, 10:56 Local Registration: N86UM Aircraft: Injuries:

Flight Conducted Under: Part 91: General aviation - Personal

Mooney M20E

On April 2, 2024, about 1056 central daylight time, a Mooney M20E airplane, N86UM, sustained substantial damage when it was involved in an accident near Alpine, Arkansas. The pilot was not injured. The airplane was operated as a Title 14 Code of Federal Regulations Part 91 personal flight.

According to the pilot, while in cruise flight in a gradual descent, the airplane's two carbon monoxide (CO) detectors began alerting, and he felt symptoms of CO poisoning. The pilot closed the cabin vents, opened a small cockpit window, and attempted to open the door, but was unsuccessful. The pilot decided to not continue the flight to the nearest airport; he shut down the engine and perform a forced landing to a field. During the forced landing, the airplane impacted unsuitable terrain and sustained substantial damage to the forward fuselage.

The airplane was retained for further examination.

#### Aircraft and Owner/Operator Information

Aircraft Make:	Mooney	Registration:	N86UM
Model/Series:	M20E	Aircraft Category:	Airplane
Amateur Built:			
Operator:	On file	Operating Certificate(s) Held:	None
Operator Designator Code:			

Page 1 of 2 CEN24LA145

# Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KHOT,505 ft msl	Observation Time:	10:53 Local
Distance from Accident Site:	19 Nautical Miles	Temperature/Dew Point:	23°C /12°C
<b>Lowest Cloud Condition:</b>	Few / 3700 ft AGL	Wind Speed/Gusts, Direction:	10 knots / 18 knots, 280°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	29.67 inches Hg	Type of Flight Plan Filed:	VFR
Departure Point:	Heber Springs, AR (HBZ)	Destination:	Tyler, TX

## **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.240469,-93.364395 (est)

### **Administrative Information**

Investigator In Charge (IIC):	Sauer, Aaron
Additional Participating Persons:	Paul J. Centinaro; FAA; Little Rock, AR
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN24LA145