

Aviation Investigation Preliminary Report

Injuries:

1 Minor

Location: Lumberton, NJ **Accident Number**: ERA24LA190

Date & Time:April 22, 2024, 21:15 UTCRegistration:N53EM

Flight Conducted Under: Part 91: General aviation - Personal

Beech B24R

Aircraft:

On April 22, 2024, at 1715 eastern daylight time, a Beech B24R, N53EM, sustained substantial damage when it was involved in an accident at the Flying W Airport (N14), Lumberton, New Jersey. The commercial pilot sustained minor injuries. The airplane was operated as Title 14 *Code of Federal Regulations* Part 91 personal flight.

Witnesses reported that the airplane's engine was running rough on takeoff. The airplane departed and subsequently lost engine power. The pilot made a forced landing to a field about 1,500 ft beyond the end of the runway resulting in substantial damage to the fuselage.

The wreckage was retained for further investigation.

Aircraft and Owner/Operator Information

| Aircraft Make: | Beech | Registration: | N53EM |
|---------------------------|---------|-----------------------------------|----------|
| Model/Series: | B24R | Aircraft Category: | Airplane |
| Amateur Built: | | | |
| Operator: | On file | Operating Certificate(s) Held: | None |
| Operator Designator Code: | | | |

Page 1 of 2 ERA24LA190

Meteorological Information and Flight Plan

| Conditions at Accident Site: | VMC | Condition of Light: | Day |
|----------------------------------|------------------|------------------------------|------------------|
| Observation Facility, Elevation: | KVAY,52 ft msl | Observation Time: | 17:54 Local |
| Distance from Accident Site: | 2 Nautical Miles | Temperature/Dew Point: | 16°C /-3°C |
| Lowest Cloud Condition: | Clear | Wind Speed/Gusts, Direction: | 4 knots / , 380° |
| Lowest Ceiling: | None | Visibility: | 10 miles |
| Altimeter Setting: | 30.05 inches Hg | Type of Flight Plan Filed: | None |
| Departure Point: | Lumberton, NJ | Destination: | Lumberton, NJ |

Wreckage and Impact Information

| Crew Injuries: | 1 Minor | Aircraft Damage: | Substantial |
|---------------------|---------|----------------------|--------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 Minor | Latitude, Longitude: | 39,-74 (est) |

Administrative Information

| Investigator In Charge (IIC): | Read, Leah |
|-----------------------------------|--|
| Additional Participating Persons: | Larry J Solley; FAA/FSDO; Philadelphia, PA |
| Investigation Class: | Class 3 |
| Note: | The NTSB did not travel to the scene of this accident. |

Page 2 of 2 ERA24LA190