



# Aviation Investigation Notification

|                                |                                      |                         |            |
|--------------------------------|--------------------------------------|-------------------------|------------|
| <b>Location:</b>               | Greeley, CO                          | <b>Accident Number:</b> | CEN26LA235 |
| <b>Date &amp; Time:</b>        | June 17, 2026, 10:50 Local           | <b>Registration:</b>    | N4275S     |
| <b>Aircraft:</b>               | Beech V35B                           | <b>Injuries:</b>        | 2 None     |
| <b>Flight Conducted Under:</b> | Part 91: General aviation - Personal |                         |            |

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

## Aircraft and Owner/Operator Information

|                                  |                        |                                       |          |
|----------------------------------|------------------------|---------------------------------------|----------|
| <b>Aircraft Make:</b>            | Beech                  | <b>Registration:</b>                  | N4275S   |
| <b>Model/Series:</b>             | V35B                   | <b>Aircraft Category:</b>             | Airplane |
| <b>Amateur Built:</b>            |                        |                                       |          |
| <b>Operator:</b>                 | EVERGREEN AVIATION LLC | <b>Operating Certificate(s) Held:</b> | None     |
| <b>Operator Designator Code:</b> |                        |                                       |          |

## Meteorological Information and Flight Plan

|                                         |                                     |
|-----------------------------------------|-------------------------------------|
| <b>Conditions at Accident Site:</b>     | <b>Condition of Light:</b>          |
| <b>Observation Facility, Elevation:</b> | <b>Observation Time:</b>            |
| <b>Distance from Accident Site:</b>     | <b>Temperature/Dew Point:</b>       |
| <b>Lowest Cloud Condition:</b>          | <b>Wind Speed/Gusts, Direction:</b> |
| <b>Lowest Ceiling:</b>                  | <b>Visibility:</b>                  |
| <b>Altimeter Setting:</b>               | <b>Type of Flight Plan Filed:</b>   |
| <b>Departure Point:</b>                 | <b>Destination:</b> Greeley, CO     |

## Wreckage and Impact Information

|                            |        |                             |                     |
|----------------------------|--------|-----------------------------|---------------------|
| <b>Crew Injuries:</b>      | 1 None | <b>Aircraft Damage:</b>     | None                |
| <b>Passenger Injuries:</b> | 1 None | <b>Aircraft Fire:</b>       | None                |
| <b>Ground Injuries:</b>    |        | <b>Aircraft Explosion:</b>  | None                |
| <b>Total Injuries:</b>     | 2 None | <b>Latitude, Longitude:</b> | 40.42817,-104.63506 |

## Administrative Information

|                                          |                                                        |
|------------------------------------------|--------------------------------------------------------|
| <b>Investigator In Charge (IIC):</b>     | Finne, Andrew                                          |
| <b>Additional Participating Persons:</b> | Jones, Jason; FAA-FSDO; Denver, CO                     |
| <b>Investigation Class:</b>              | <a href="#">Class 4</a>                                |
| <b>Note:</b>                             | The NTSB did not travel to the scene of this accident. |